

**To:** Stan Kaczmarek[StanK@demaximis.com];  
hammondbh@cdmsmith.com[hammondbh@cdmsmith.com]  
**Cc:** John Rolfe[jrolfe@demaximis.com]  
**From:** Hoppe, Michael  
**Sent:** Thur 4/3/2014 3:21:09 PM  
**Subject:** RE: 10.9

All,

If it looks like the shroud is going to be installed this afternoon, let me know. Same for panel placement. If may still come up to the river, but if neither is happening, then I'll save the trip.

Thanks.

Michael Hoppe  
Federal On-Scene Coordinator  
USEPA Region 2  
Response and Prevention Branch  
Preparedness Section  
Phone: (732) 906-6908 Fax: (732) 321-4425  
Cell: (908) 420-4472

-----Original Message-----

From: Stan Kaczmarek [mailto:StanK@demaximis.com]  
Sent: Thursday, April 03, 2014 11:16 AM  
To: hammondbh@cdmsmith.com; Hoppe, Michael  
Cc: John Rolfe  
Subject: Re: 10.9

Been told it is not looking good for fabric placement today. Still need to see. The new shroud was delivered yesterday but I do not believe it is hooked up. John Rolfe is on site today and he can update all of us as the day progresses.

>>> &quot;Hoppe, Michael&quot; <Hoppe.Michael@epa.gov> 04/03/14 10:37 AM >>>  
Flow at dam looks like it is still up (4700+ cfs). Any chance at panel placement today? Also did the upgraded assembly come in for the poseidon barge?

Michael Hoppe  
Federal On-Scene Coordinator  
USEPA Region 2  
Response and Prevention Branch  
Preparedness Section  
Phone: (732) 906-6908 Fax: (732) 321-4425  
Cell: (908) 420-4472

[ER logo (R2 modified CAPs lsmall)]